

# Easy way to compute dewpoint temperature in a humid environment

- Only works if  $RH > 50\%$
- $T_D = T - \frac{(100 - RH)}{5}$
- $T$  and  $T_D$  must be in Celcius